SIHI LIQUID RING VACUUM PUMP TROUBLE SHOOTING GUIDE

IDENTIFIED PROBLEM	CAUSE	EFFECT	CORRECTIVE ACTION
EROSION Characteristics: smooth, clean, grooved surfaces and edges.	Presence of sand, grit and other abrasive material.	Accelerated wear of impeller blades especially at the periphery. Premature wear of intermediate plate, centerbody & endcover(s).	 Filter the service liquid. Add pre-separators at the pump inlet. Select proper pump materials.
CORROSION Characteristics: Usually uneven, scaled on blackened surfaces and edges. Will occur on all wetted areas including impeller blade roots.	Chemical attack of wetted pump parts (usually by acidic low pH). Sources may be vapors or liquids from the process or from the service liquid.	Accelerated damage of the impeller, intermediate plates, center body & endcover(s).	 Monitor service liquid pH & treat as necessary. Purge the service liquid loop on a regular basis. Look for source of corrosives and treat or remove. Change to a pump material e.g. stainless steel, that will not corrode.
FLOODING THE PUMP	Service liquid rate is too high. Pump starts flooded. Carryover from the process.	Impeller blades fatigue failure of shaft. Shaft deflection in single acting pumps possible, leading to mechanical seal leakage, high motor amperage.	 Check the service liquid rate for the specific pump. Piping may be installed incorrectly. Pump should drain to the centerline after shutdown. Check for proper pump inlet separation.
CAVITATION DAMAGE	Liquid temperatur e too high. 2. Vacuum too high.	Holes or pitting at the tips and roots of the impeller blade and intermediate. Grinding noise when pump is running.	 Lower the service liquid temperatures or increase the flow of service liquid. Lower the vacuum level. (increase the pressure)

	1		
VIBRATION	Incorrect installation of foundation	Broken couplings, worn V-belt drives or broken foundation bolts.	Check with Sterling SIHI on proper foundation and grouting procedures.
	Poor coupling or V-belt drive alignment	Pump bearings may fail prematurely.	Check alignment or call Sterling SIHI for assistance.
	·		Check for proper preseparation
	3. Slugs of water carry-over to the pump inlet.		Add flexible connections if necessary.
	4. Piping stress at the inlet discharge or service liquid connection s.		5. Pump should be sent to Sterling SIHI for repair. Inlet screens should be installed before pump is started to insure material does
	5. Pump ingested foreign material i.e. bolts, nuts, weld slag.		not enter pump. 6. Repair or replace worn & damaged parts.
	6. Internal damage due to cavitation, corrosion, etc.		
INGESTION DAMAGE	No inlet screens on the pump or compressor	Broken impeller blades or seized pump.	Return pump to Sterling SIHI for repair evaluation.
SCALE	Hard service liquids i.e. lime or mud. Pumps running hotter will accelerate this problem.	a. Scaling will close the internal pump clearances & cause binding.	Use suitable descaler, but flush after use. Consult with Sterling SIHI for recommendations on the type and quantities.
		b. Scaling will cause a decrease in pump	

	performance	9.
	c. Scaling will slowly close the service liquid lines and cause the pump to run warmer.	
BEARING FAILURE	Not using the recommen ded lubricant. Seized pump and broken or damaged bearing housing.	Check the Sterling SIHI manuals for recommended lubricant. Check & clean
	2. Over or	bearings. (replace if worn)
	under greased.	3. Check alignment & foundations for proper support.
	Couplings or V-belt drives not properly	4. Use flexible
	mounted or aligned.	connections for pump inlet, discharge and service liquid lines.
	4. Piping not properly supported and/or aligned.	5. Check mechanical seals or packing. Shield bearings if environment is wet.
	5. Water in the bearings.	6. Consult Sterling SIHI for assembly dimension or return for repair evaluation.
	6. Internal pump clearances set improperly.	

PUMP RUNS WARMER	1. Insuf		ity levels for cuum pump or	1.	Check the manuals or call Sterling SIHI for
THAN NORMAL		d flow. compredections	essor may e. Also the n level may		the proper service liquid flow.
	of hi	eratur	·	2.	Check for proper preseparation or call a Sterling SIHI technician.
	of hi	eratur		3.	High gas temperatures may be a process condition that may be unavoidable. Adjust service liquid flow as required. Call Sterling SIHI if problem persists.
	may highe	p RPM be er than mmen		4.	Check pump RPM for the service. Call if necessary.
PUMP LEAKS	mech seal. some leaka nece to ke pack cool. tighte will h	ing or Note when some and age is essary eap the ing (Over ening arden, ome & score bump	f service liquid. ial gas leakage shut down. In cases this may ouse keeping m. In major this may lead r pump nance or e to the pump.	1.	Check packing and tighten or check & replace mechanical seal. Service liquid or contaminates from the process can coat or abrade mechanical seal faces.
	2. Leak could from body gask drain (Som s a re	age d be		2.	Check the source of the leak. Repair may be necessary.

LUCLED 1 Dissert Assuming Assuming to the	Covitation and by
THAN cavitating. noise level is an early indication of a	Cavitation can be a complex problem. Consult with Sterling SIHI for solutions.
2. Pump is overloaded failure. Potential vibration concerns.	Check for proper service liquid flow. Also check for good inlet pre-separation.
3. Pump has ingested foreign material.	Stop the pump immediately. Disassemble and inspect or send the pump to Sterling SIHI for repair evaluation.
4. Bearings t	Inspect bearings. See the subject of bearing failures.
5. Pump	Coupling and V-belt drive alignment must be checked.
LEVEL design. are usually lower	See the section dedicated to piping design.
than recommen ded service	The addition of heat exchangers, cooling towers or chillers may be required. Consult with Sterling SIHI.
es. 3. 0	Check the manuals or call Sterling SIHI for proper service liquid flow.
	Check for proper preseparation.
4. Liquid	

carryover to the pump inlet.	5. Check application needs and call Sterling SIHI for assistance.
5. Improper pump application.	6. Consult with Sterling SIHI for sizing and selection of relief valves or revised vacuum control needs.
6. Poor or insufficient vacuum control.	